

## R3xx Firmware Revision History

In order to find out the revision of your module's firmware use the "ATI<cr>" command.

If you are an existing customer and want to update your firmware please contact [zigbeesupport@telegesis.com](mailto:zigbeesupport@telegesis.com)

### **R301 – 16-09-2008**

#### Changes

- Upgraded from EmberZNet3.1 to EmberZNet3.2
- Fixed Problem with specifying EPID in S03 on joining Node
- Removed functionality 0018 temporarily for memory savings
- Fixed cloning to End Devices from Nodes other than the Parent
- Improved cloning mechanism. AT+CLONE can also address NodeIDs and Address table indexes (when cloning to devices >R300).
- It is now possible to write to address table entry 05 (sink entry)
- Data sent to endpoint 0 and 2 is now displayed transparently (if enabled)
- Added bit 2 of S0F to enable displaying all sink advertisements (disabled by default). New Prompt: ADSK:<EUI64>,<NodeID>
- Added bit 7 of S10 to stop node from replacing existing sink with better one (lower cost)
- Added volatile S46 for data related to start-up functionality.
- Contents of S46 (16 bit number) is attached to tracking messages (functionality 0112 and 0113)
- Fixed ATSALL triggering replies
- Added bit A of S0A to disable joining nodes to ask for the Trust Centre link key.
- Improved Trust Centre EUI64 caching
- Fixed Source Route handling
- AT+FNDSR is now working at ZDO Level (works with 3<sup>rd</sup> party nodes), but only when addressed with EUI64 or address table index.
- Debouncing now operates on all 4 IRQ inputs when enabled and works in sleep modes
- Fixed sending SCASTBs with a payload smaller than 5 bytes
- ETRX3: Fixed GPIO misconfiguration when enabling PWM output on PB7

#### Registers and Commands affected

- S03
- functionality 0018
- AT+CLONE
- S0F
- ATSALL
- S0A
- AT+FNDSR

#### Indirectly affected

Nothing

#### Upgrade information available

None

#### Upgrade Note Details

For the new cloning mechanism the user needs to ensure that the target device is just a single hop away before initiating the cloning process. If this is not the case the remote node will remain in the bootloader until reset or recovered using AT+RECOVER.

## R302 – 30-04-2009

### Changes

- Upgraded to EmberZNet3.3.3
- Fixed AT+N providing odd results if node is not part of a network
- Fixed functionalities 0012 to 0014 to cause routers to re-join non existing networks three times.
- Added functionality 0018
- Setting bit 9 of S0A on the ZC before starting the network will start the network without the use of a central Trust Centre (distributed Trust Centre mode, not ZigBee compliant). Note: Only a global link key can be used, so Setting bit 7 of S0A will be ignored in this mode)
- Added command AT+BECOMETC to allow the ZC in a network which has been started with a distributed TC to become the TC.
- Setting Bit D of S10 changes the sinks and Trust Centre to be of type EMBER\_HIGH\_RAM\_CONCENTRATOR. This will cause remote nodes not to send a source record message only before the first message sent to the sink or Trust Centre and not repeatedly.
- Sinks also send a many-to-one route request via functionality 02xx and create aggregation routes
- AT+PING and replies to AT+SN use ZDO device announce messages for improved ZigBee compatibility
- ADSK prompt is only shown for sink advertisements of sinks, which aren't the local node's sink
- Shortened S0B to 16 characters.
- Fixed functionalities 0108 and 0109 to only send a maximum of 47 characters
- Fixed deep sleep IRQ handling
- Added S47 to represent the Node's Power Descriptor
- Added S48-S4B to configure the Node's second endpoint
- Added new ZDO commands for Device and Service Discovery: AT+IDREQ, AT+EUIREQ, AT+NODEDESC, AT+POWERDESC, AT+ACTEPDESC, AT+SIMPLEDESC, AT+MATCHREQ
- Improved Cloning Mechanism
- Re-Introduced the AT+DMODE command (known as AT+OPCHAN in R2xx) to create a serial link between any two devices
- Added possibility to join as non sleepy end device (RX on when idle) by modifying the meaning of bits E and F in S0A. New Device type is called ZED.
- Changed formatting of the AT+NTABLE command
- Improved Network Formation and Joining
- Changed S-Registers to not do a Network Key update automatically from the COO and added command AT+KEYUPD to do this manually.
- Source Routes get deleted in case of unsuccessful delivery of a unicast, unless bit D of S10 is set
- Added S4D, S4E and S4F for expert stack timing adjustments
- Improved remote S-Register access to allow concurrent accesses.
- Inverted functionality for bit 8 of S10 to prevent frequent broadcasts to search for sink
- Added Data mode (in R2xx known as "channel")
- Changed S28 to trigger on Network Join
- AT+PING renamed to AT+ANNCE for clarity (AT+PING is still supported for backward compatibility)
- Changed format for response to AT+NTABLE to be inline with other ZDO prompts
- End Devices, which have lost their parent will report "LostPAN" instead of "LeftPAN" as they are still part of the PAN and simply can't talk to it any more. AT+N will still show the network parameters. Use AT+REJOIN or simply poll to find new parent or AT+DASSL to leave.
- In case a parent knows a sink it will pass it on to any joining end device. In case the parent's sink gets updated the parent will update all children using a broadcast.
- Added functionality 0400 (known as 0200 in R2xx).
- Improved AT+FNDSR
- Replies to ATREMS have been re-formatted for better usability

### Registers and Commands affected

- AT+PING
- AT+SN
- AT+CLONE
- S0A
- AT+NTABLE
- ATREMS
- S28

### Indirectly affected

Nothing

### Upgrade information available

none

### Upgrade Note Details

- "FFD" and "COO" prompt have been combined into "FFD"
- Formatting of ATREMS has changed
- After upgrading a factory reset will be conducted
- Cloning between R301 and R302 won't work
- By default nodes don't search sink automatically if none is known to prevent frequent broadcasts (bit8 of S10)

## R303 – 07-04-2010

### Changes

- Upgraded to EmberZNet3.5.1 (ETRX2)
- Upgraded to Ember ZNet4.0.2 (ETRX3)
- Fixed wakeup by UART to interfere with other external interrupt's functionality
- Fixed NodeID MSB and LSB mix-up in reply to AT+SN and AT+ANNCE and S07
- Fixed MCASTs not getting through to both endpoints
- ADC calibration now only performed when needed. Significantly shortens awake interval for sending messages containing ADC readings.
- Added interaction with ETRX3 series 32 bit S-Registers
- Modified "RX:" prompt to include sender's EUI64 and Node ID:  
RX:[<EUI64>],<NodeID>,<profileID>,<destinationEndpoint>, <SourceEndpoint>,<clusterID>: <payload>
- Added functionality 0401 to use separate IO for indication
- Non-sleepy EDs are polling as well when functionality 0010. This is just to prevent them from timing out at their parent
- ETRX2: Fixed Data Mode malfunctioning when command echo is switched off
- Corrected default value of S4E to 0605 (5 Minutes)
- ETRX3: Corrected major bug with I/O configuration when going into power modes 2 and 3
- ETRX3: Fixed S0D to also show the firmware revision
- Fixed Functionalities 24xx to 26xx
- ETRX3: Fixed Charging External RC for functionalities 0111 and 0113
- ETRX3: Fixed functionalities 0400 and 0401
- ETRX3: Fixed IRQs triggering on both edges in power modes 2 and 3
- ETRX3: Fixed potential issue with timers stopping when waking up from sleep
- Added AT+RTABLE (ZDO) command
- S4B and S4C extended to hold up to 12 cluster IDs
- S46 is now a 32-bit number
- ETRX3: Fixed RDATA Messages
- ETRX3: Setting bit 8 of S15 enables Vref output on PB0
- Added functionality 0114 and 0115 to send tracking message, which doesn't contain ADC readings.
- Fixed mixing up MSB and LSB of a Device Announce
- Changed default power setting to 3dBm for both hardware platforms. Power settings above 3dBm will automatically enable the boost mode.
- Improved timer accuracy when repeatedly woken up by external interrupts from power mode 2.

#### Registers and Commands affected

- S07
- AT+RTABLE
- S4B, S4C
- S46
- S15
- S01

#### Indirectly affected

The 16-bit short address of a node reported using AT+ANNCE (AT+PING) or as a reply to AT+SN will be shown with the least significant byte first in case the remote node using a previous version of this firmware.

#### Upgrade information available

None

#### Upgrade Note Details

After upgrading a factory reset will be conducted

## R304 – 17/09/2010

### Changes

- Upgraded to EmberZNet4.2.0 (ETRX2 and ETRX3 series)
- First Release for the ETRX351 family
- Prompt for receiving data on custom endpoint modified to include the length of the incoming message: RX:<profileID>,<destinationEndpoint>, <SourceEndpoint>,<clusterID>,<payload length>:<payload>
- Hardened Response to AT+N
- Fixed Parameter entry for AT+SN
- Hardened UART buffer handling
- Added AT+PASSTHROUGH command for passthrough bootloading on the ETRX3 series
- Added the "ENTERING BLOAD" prompt to be displayed when a device is brought into the bootloader remotely (using AT+CLONE on the ETRX2 series or AT+PASSTHROUGH) on the ETRX3 series
- Modified AT+RECOVER command on the ETRX3 series to recover from failed passthrough bootloads
- ETRX3: Fixed S19 not being copied into S18 after reset
- Fixed RF power changing back to normal after reset when bit 3 of S10 was set during a change of S01
- ETRX3: Fixed S3F not having any effect
- It is now possible to completely erase S4B and S4C by entering "ATS4B=" or "ATS4C=" respectively
- Added AT+SJN for "silent joining"
- Fixed watchdog timer triggering when node is due to go to sleep, but flow control is preventing it from sending pending information to host
- Optimized throughput of the channel
- Implemented network manager functionality. By default the COO is the network manager.
- Added AT+BECOMENM command for node other than the COO to become network manager
- Added AT+CCHANGE command for the network manager to change the network's channel
- Added "NM:ES REPORT WARNING" callback to indicate high number of unicast failures in the network reported to network manager
- Added Bit 6 of S0F to hide Network Manager Warning
- Added functions 0130 and 0131 to send ADC data and counter register S46

### Registers and Commands affected

- AT+SJN
- AT+PASSTHROUGH
- AT+BECOMENM
- AT+CCHANGE
- AT+SN
- S0F, S18, S3F
- Function 0130

### Indirectly affected

- If flow control prevents the node from sending its data before going to sleep for more than 10ms the node will go to sleep without sending its data

### Upgrade information available

None

### Upgrade Note Details

- Passthrough bootloading on the ETRX3 series will only work if the receiving node has a recent OTA capable bootloader (v42 or later)
- The ETRX351 family of the firmware is now denoted by "351", e.g. "ETRX351\_R304C.ebl". The ETRX351 and ETRX357 firmwares are not interchangeable
- When R304C is loaded on to an ETRX357-LRS, it is necessary to activate the RF power amplifier with the comands "ATS178=1" and "ATS198=1" followed by a reset

## R305 – 03/03/2011

### Changes

- Upgraded to EmberZNet4.3.0 (ETRX2 and ETRX3 series). This should lead to a significant power savings on sleepy end devices
- First Release for new "-LRS" variants
- ETRX3: Increased UART TX queue size to 256 bytes
- Added support for processor idling to save additional power in power modes  $\geq 1$
- Fixed functionality 0130 repeating the 16 least significant bits of S46
- (non sleepy) End Devices will receive sink advertisements directly and not via their parents
- Improved sink address handling on Sleepy and Mobile End Devices
- Sleepy and Mobile end devices get told the address of their parent's sink automatically after joining
- When receiving a tracking messages triggered by functions 0112-0115 a sink will also prompt a "TRACK" or "TRACK2" message locally to report its own RSSI reading
- Fixed ZDO requests to the COO crashing the COO (eg when reading its neighbour table)
- ETRX3: Fixed AT+EN failing when a specific network is specified in S00 and S02 which already exists. AT+EN will now form a network with a random PAN ID instead as specified in the AT command dictionary
- Moved triggering S27 "Functionality at Bootup" to after the stack is initialized.
- ETRX3: Fixed Functionality 005x and 006x
- The default power level out of the EM35x for the ETRX35x-LRS and ETRX35xHR-LRS has been set to -11dBm to comply with European regulations. The highest allowable power setting has been restricted to -7 which results in 20dBm output power.
- The default channel mask for the ETRX35x-LRS and ETRX35xHR-LRS has been set to 0x7FFF to disable channel 26, which only allows limited power output in some countries
- Improved DMODE in that data is send faster when at the same time there is incoming data
- Added bit 8 of S0F to show messages received on endpoints 3 and higher
- Added bit 7 of S0F to hide AddrResp prompts
- ETRX2: enabled pull-ups and pull-downs on TXD and RXD
- Improved hardware handshaking to prevent buffer overflow causing a reset
- ETRX2: Force a token Reset when first installing R305, so downgrading to versions prior to R304 (ZNet3 causes a token Reset and eliminates problems with the different token systems of ZNet3 and ZNet4)
- Eliminated requirement to wait for ">" sign when sending xCASTBs
- ETRX3: Fixed S40 mixing up source and destination endpoints during read access
- ETRX2: Fixed AT+SJN

#### Registers and Commands affected

S0F  
S13, S14  
S27  
S40

#### Indirectly affected

#### Upgrade information available

None

#### Upgrade Note Details

- ETRX2: After upgrading a factory reset will be conducted
- AT+SJN will always assume a NetworkKeySequenceNumber of 0

## R306 – 21/10/2011

### Changes

- Upgraded ETRX3 series to EmberZNet4.5.3.1
- Upgraded ETRX2 series to EmberZNet4.3.5
- ETRX3 series: Increased maximum number of children per router to 64
- Fixed AT+DASSR to not sometimes disassociate child nodes of the remote node as well as the remote node itself
- Fixed function 0113 not returning output pin to high-Z
- Fixed problem of ETRX2-PA sending Error 0F with certain power settings
- When an invalid baudrate is set in S12 the node will default to a baudrate of 19200
- Clarifications in the AT Command Manual
- ETRX2: Fixed stack bootup issues with bit 3 of S10 set and S01 modified whilst the node is part of a network
- ETRX2: Improved accuracy of the 250ms time-base in power mode 0
- ETRX2: Fixed input pull-ups and pull-downs not working
- Fixed DMODE link not closing when one device is reset
- "Length" returned by AT+NTABLE and AT+RTABLE is more reliable
- AT+CCHANGE now also takes into account the channel mask defined in S00
- ATREMS can read local node (use FF as the address)
- Added bit D of S0A so that a router can be prevented from actually routing messages
- Added bit C of S0A to add a prescaler of 2<sup>8</sup> (256) to the PWM
- Added bit E of S0F to show RSSI of incoming messages
- Added bit F of S0F to add wrapper to local S-register reads
- ETRX3 series: Fixed bit A of S0A having no effect
- Fixed searching a sink for only a single hop
- Non-sleepy end devices now obtain their sink from parent
- Improved sink address acquisition for Sleepy End Devices
- Fixed <stx><etx> being disabled when xCAST wrapper is off (S0E bit 5)
- Fixed potential hang-up when SED has lost its parent
- ETRX357 – fixed changes to S16 stopping the PWM
- ETRX357 – fixed PWM not running after a reset even though S11 bit F is set
- Added function 001E to detect a missing coordinator
- Added functionality 0x0116 to 0x0119 to filter tracking messages by RSSI
- Added functionality 0x0020 and 0x0021 to switch PWM when network is lost
- Factory Reset Tool now works even if the serial port is disabled in S15

### Registers and Commands affected

- AT+DASSR
- AT+NTABLE
- AT+RTABLE
- AT+DMODE
- ATREMS
- S12, S13, S14
- S0A
- S0F
- Functions 0020, 0021
- Function 001E
- Functions 0116-0119
- Function 0113

### Indirectly affected

### Upgrade information available

None

### Upgrade Note Details

- After upgrading a factory reset will be conducted

## R307 – 14/5/2012

### Changes

- Upgraded to EmberZNet4.6.4 (ETRX2 and ETRX3 series).
- First Release for new "-ERS" variants of the ETRX3 series
- Fixed Power mode 1 not being entered after Reset when preset in S3A
- ETRX3: PA7 can be configured as UART TX\_ACTIVE in S15
- ETRX3: Bit 23 of S15 can be used to switch PC6 to nTX\_Active
- Added functionality 001F
- ETRX3: Maximum level for S01 limited to -7 on LRS devices.
- Modified power management to support the new Znet4.6.x features.
- ETRX3: Added new commands for Binding management using the ZDO
- ETRX3: Added Binding table
- ETRX3: AT+UCAST(B) and AT+MCAST(B) can now also use a Binding table entry as target address
- ETRX3: when using destination address FE, binding table is searched against S40 and S42 for the first entry that matches source endpoint and cluster ID
- ADC is auto-calibrated every 1000<sup>th</sup> measurement
- ETRX3: By setting bit 23 of S11 PC7 will indicate the status of the DMODE (high = active, low = inactive). PC7 needs to be defined as output in S16 and can be overridden using S18
- The Power level set in S01 takes effect before joining a network
- ETRX2: Increased Address Cache Size to 19
- Extended the Address Table by one entry (06) which contains the address of the sender of the last incoming UCAST, SCAST or BCAST
- S11 bit E (enable boost mode) now takes effect immediately instead of needing a reset
- S0B, S3B & S3C can now contain non-printing characters, including \0
- SEDs and MEDs in power mode 2 no longer draw high current when they lose the PAN

### Registers and Commands affected

- AT+LBTABLE
- AT+BSET
- AT+BCLR
- AT+BTABLE
- AT+BIND
- AT+UNBIND
- S11
- S15
- S3B & S3C

### Indirectly affected

### Upgrade information available

None

### Upgrade Note Details

- After upgrading a factory reset will be conducted

## R308 – 25/6/2012

### Changes

- Fixed bug that restricted the number of end devices per router
- Corrected response to ATREMS where <etx> was not the final character
- Fixed ETRX357-LR not having PC5 configured automatically as TX\_active
- Corrected response to bootloader option 3

### Registers and Commands affected

- ATREMS
- AT+BLOAD
- S15

### Indirectly affected

### Upgrade information available

None

### Upgrade Note Details

- After upgrading a factory reset will be conducted

## R309 – 30/07/2015

### Changes

- Updated to Znet5.4.0
- 
- Bit 1 of S0A disable the display of received interpan messages when set
- Bit 6 of S0A appends RSSI and LQI to "RX:" prompts
- Unless Bit 1 of S0F is set unhandled messages received by Endpoint 1 are now also displayed using the "RX:" prompt (Bit 1 of S0F is a high level disable for the "RX:" prompt).
- Bit 8 of S0F is now used to enable showing unhandled messages sent to endpoint 1 and above (formerly 3 and above).
- Bit 9 of S0F can be used to disable the SWRITE Prompt
- Bit A of S0F adds remote endpoint and NodeID to the ACK and NACK prompts in the format ACK:<sequence in 8-bit hex>,<endpoint in 8-bit hex>,<NodeID in 16-bit hex> for profile Ids other than the default Telegesis one
- Bit B of S0F enables NODELEFT prompt at coordinator to indicate that a device left the PAN
- Bit C of S0F causes message payload of RX prompt to be displayed as hexadecimal instead of ASCII characters
- Bit D of S0F can be used to disable handling ZDO exchanges other than by using the RX prompt
- Bit E of S0F also adds RSSI to AT+PANSCAN report
- 
- Increased MAC timeout in S4F to 7.68s to match Home Automation recommendations
- Fixed rare (<1ppm) occurrence of TX character loss due to non interrupt save code
- Fixed beginning response to AT+TOKDUMP with "\r\n"
- Fixed doing a re-join instead of a clean join in case of joining a network the node was previously part of
- Improved throughput of the DMODE by triggering sending of packets 20ms after the last incoming character was received.
- Increased TX buffer of serial port to 256 bytes
- Fixed output power reverting back to the level the network was joined with after a reset in case S103 is set and power was changed in the meantime
- Fixed AT\$ALL broadcast addresses being overwritten by S102
- Fixed incorrect destination endpoint in RX prompt when message is a multicast
- ETRX357-LRS and ETRX357HR-LRS modules are programmed with the MFG\_CCA\_THRESHOLD token set to offset the gain of the LNA
- ETRX357-LRS and ETRX357HR-LRS modules have default power setting in S01 reduced to -17
- ETRX3 Modules natively programmed with R309 are programmed with the updated standalone bootloader R102.
- Tracking messages are only sent when device is in network
- Removed extraneous byte from payload of AT+SIMPLEDESC
- Fixed AT+LBTABLE not displaying the full table
- Prompts "Bind" and "Unbind" are now terminated using \r\n
- Binding Table size had to be reduced down to 24 entries to save simulated eeprom space
- Firmware now ensures background scan for joinable networks is completed before executing new active or passive scan
- Fixed invalid APS frames sent by functionality sending messages triggered by S28 (at network join)
- Fixed incomplete command being completed by the data of previously executed command
- Increased blacklist for AT+JN from 4 to 10 Networks
- Added Power Mode 4, which is identical to PowerMode 3 except that device does not wait for any pending acks before going to sleep
- COO and routers cannot be put into a sleep mode
- 
- Added AT+REMZ Command to reset remote node
- Added AT+EDBIND to request end device binding
- Added AT+SENDUCAST, AT+SENDUCASTB, AT+SENDMCAST and AT+SENDMCASTB commands to send more generic ZCL and ZDO messages
- Added AT+INTERPAN and associated receiver prompt
- Added time commands AT+SETTIME, AT+GETTIME, AT+SYNCTIME
- AT+PANSCAN now has parameters to filter responses by joinability and channel mask. Scan window length can be altered. RSSI can be reported
- AT+KEYUPD will distribute the Key provided in S08 instead of a random key when the key in S08 is valid (non zero) and is not currently in use.

## R309 – 30/07/2015

- Functionality 0018 can now also address multicast bindings (only) when binding ID is specified in S3B
- Added functionality 0402 to allow other GPIOs to be used for indication
- Fixed function 2001 losing the first three characters after a reset
- Fixed function 24xx not controlling other timers properly
- Added build in functionality 53xx,54xx,55xx and 56xx to mirror functionality of 003x,004x,005x and 006x, with extended parameter range to suit increased GPIO count on ETRX3 series modules

### Registers and Commands affected

- AT+JN
- AT+LBTABLE
- ATSALL
- AT+SIMPLEDESC
- AT+EDBIND
- AT+SENDUCAST
- AT+SENDUCASTB
- AT+SENDMCAST
- AT+SENDMCASTB
- AT+INTERPAN
- AT+SETTIME
- AT+GETTIME
- AT+SYNCTIME
- AT+KEYUPD
- AT+REMZ
- AT+DMODE
- AT+PANSCAN
- S01
- S0A
- S0F
- S10
- S11
- S39/S3A
- S4F

### Indirectly affected

### Upgrade information available

R309 is not available for the ETRX2 series

### Upgrade Note Details

-